

HW 8, Answers

1. First step is to verify that the problem is feasible

$$\sum \frac{d_j}{P_j} = \frac{5600}{20000} + \frac{5600}{30000} + \frac{5600}{20000} = 0.7521 < 1, \text{ so there is a feasible solution}$$

$$\begin{aligned} h_j^1 &= \left(1 - \frac{d_j}{P_j}\right) \cdot h_j \\ \Rightarrow h_1' &= \left(1 - \frac{5600}{20000}\right) \times 3000 \times 0.2 = 432 \\ h_2' &= \left(1 - \frac{5600}{30000}\right) \times 2500 \times 0.2 = 406.7 \\ h_3' &= \left(1 - \frac{5600}{20000}\right) \times 4000 \times 0.2 = 576 \end{aligned}$$

Setup costs:

$$\begin{aligned} K_1 &= 4000 \quad K_2 = 2000 \quad K_3 = 3000 \\ \Rightarrow T^* &= \sqrt{\frac{2 \cdot \sum K_j}{\sum h_j' d_j}} = \sqrt{\frac{2 \times (4000 + 2000 + 3000)}{(432 + 406.7 + 576) \times 5600}} \\ T^* &= 0.0477 \text{ years} \\ &\text{check whether } T^* > T_{\min} \\ T_{\min} &= \frac{2/(5 \times 50) + 0.5/(5 \times 50) + 1/(5 \times 50)}{1 - 0.75} = 0.056 \\ &\text{since } T^* < T_{\min} \Rightarrow \text{choose } T_{\min} = 0.056 \\ \Rightarrow Q_1^* &= d_1 \cdot T_{\min} = 3136 \quad Q_2^* = Q_3^* = 3136. \end{aligned}$$

$$2. \text{ Cost of in-house production} = \sum_{j=1}^3 \left( \frac{K_j}{T_{\min}} + h_j' \cdot \frac{Q_j}{2} + c_j \cdot d_j \right)$$

$$\begin{aligned} &= \frac{4000}{0.056} + 432 \times \frac{3136}{2} + 3000 \times 5600 \\ &+ \frac{2000}{0.056} + 406.7 \times \frac{3136}{2} + 2500 \times 5600 \\ &+ \frac{3000}{0.056} + 576 \times \frac{3136}{2} + 4000 \times 5600 \\ &= 55,578,963.89 \cong 55,578,964 \end{aligned}$$

Outsourcing cost was 68,266,017.42  $\Rightarrow$  since cost of producing in-house is lower  $\Rightarrow$  shift to in house.

To recover  $\Rightarrow \frac{10000000}{12687054} = 0.788$  years required

However, in general, other issues should also be considered in choosing between in-house production and outsourcing. Such as quality differences, possibility of a significant (downward or upward) shift in demand, potential development of new technology (which could require an investment in a new machine often), lead times, and necessity/possibility of using the same machine for other products of the company.

# Solution to Problem 2

## In HW # 3

---

a)  $C_0 = 22 - 10 = 12 \text{ \$ / unit}$

$C_u = \text{profit} = 50 - 22 = 28 \text{ \$ / unit}$

b)  $F(Q^*) = \frac{C_u}{C_u + C_0} = 0.7$

$\Rightarrow \Phi\left(\frac{Q^* - \mu}{\sigma}\right) = 0.7$

$\Rightarrow$  From table A.1  $\frac{Q^* - \mu}{\sigma} = 0.53$

$\sigma = 2000 \quad \mu = 6000$

$\Rightarrow Q^* = \underline{7060}$

c)  $F(Q^*) = 0.7$

$\Rightarrow \frac{Q^* - 4000}{6000 - 4000} = 0.7 \Rightarrow Q^* = \underline{5400}$

d)

Q	2000	3000	4000	5000	6000	7000	8000	9000	10000
F(Q)	0.02	0.05	0.15	0.3	0.6	0.75	0.9	0.95	1

$F(Q^*) = \boxed{0.7}$

in here  
 $\leftarrow$  so by interpolation

$\frac{Q - 6000}{7000 - 6000} = \frac{0.7 - 0.6}{0.75 - 0.6} \Rightarrow Q^* = \underline{6667}$